

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Confirmation No.: 9589

Patent No. : 7,078,296
Patentee : Fairchild Semiconductor Corp.
Title : SELF-ALIGNED TRENCH MOSFETS AND METHODS
FOR MAKING THE SAME
Issued : July 18, 2006
Docket No. : 17732.41020

Attention Certificate of Corrections Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

Sir:

In accordance with 37 CFR § 1.323, Assignee requests that the attached Certificate of Correction (Form PTO/SB/44) be issued to correct mistakes in the above-identified patent. As shown below, the mistakes are: (1) of a clerical, typographical, or minor nature, and (2) correction of the mistakes would not constitute new matter or require reexamination.

As shown in the attached Certificate of Correction, the mistakes relate to two errors in the specification, and to reference numeral errors in Figures 6 and 8. With respect to the specification, "13" should be deleted from "surface 13" in column 2, line 32 because numeral 13 is not shown in Figure 3—and column 2, line 22 implies that all numerals in that paragraph are shown in Figure 3. Moreover, "remained" should be replaced with "remain" in column 3, line 49 to correct the self-evident typographical error.

With respect to the drawings, numeral 23 should be replaced with numeral 24 in Figure 6 because the discussion of Figure 6 in the specification describes the element as numeral 24 and does not mention a numeral 23 (see column 4, line 6 et al.). As for Figure 8, numerals 25 and 26 should be combined and replaced with numeral 24 because the discussion of Figure 8 in the specification (see column 4, lines 27-43 et al.) references numeral 24 and not 25 or 26.

Enclosed is a check in the amount of \$100.00 due under 37 CFR § 1.20(a). The Director is authorized to charge and any other fee required for acceptance of this paper, or credit any overpayment, to Deposit Account No. 50-0843.

Respectfully submitted,

Date: January 10, 2007

By


Kenneth E. Horton
Reg. No. 39,481

KIRTON & McCONKIE
1800 Eagle Gate Tower
60 East South Temple
Salt Lake City, Utah 84111
Telephone: 801-328-3600

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO: 7,078,296

Page 1 of 2

APPLICATION NO: 10/052,234

ISSUE DATE: 7/18/2006

INVENTOR(S): Duc Chau et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

- 1) At Col 2, Line 32, delete "13" from "surface 13"
- 2) At Col 3, Line 49, replace "remained" with "remain"
- 3) In Figure 6, replace numeral 23 with the numeral 24

MAILING ADDRESS OF SENDER: Kenneth E. Horton
KIRTON & McCONKIE
1800 Eagle Gate Tower
60 East South Temple
Salt Lake City, Utah 84111
Telephone: 801-328-3600

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hours to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you are required to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing this form, call 1-800-PTO-9199 and selection option 2.

PTO/SB/44 (04-05)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO: 7,078,296

Page 2 of 2

APPLICATION NO: 10/052,234

ISSUE DATE: 7/18/2006

INVENTOR(S): Duc Chau et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

4) In Figure 8, replace numerals 25 and 26 with the numeral 24 as shown below:




FIGURE 8

MAILING ADDRESS OF SENDER: Kenneth E. Horton
KIRTON & McCONKIE
1800 Eagle Gate Tower
60 East South Temple
Salt Lake City, Utah 84111
Telephone: 801-328-3600

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hours to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you are required to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing this form, call 1-800-PTO-9199 and selection option 2.